



BELL HELICOPTER 407

General Information

Date: July 24, 2016

Manufacturer: Bell Helicopter Textron Canada Ltd

Year Model: 1999

Location: Europe

Model: 407

Serial Number: TBA

Registration: EASA

Detailed Description

Helicopter Hours: 2170 TTSN

Engine: Rolls-Royce Corporation 250-C47B

Serial Number: TBA

Hours: 2170 TTSN

Landings: UNK TCSN

Avionics / Equipment

King KY-196A Comm

King KT-76A Mode C Transponder

King KLN-89B GPS

HSI

King KY-155 Nav/Comm

King KR-87 ADF

King KMA-24 Audio Panel

406 MHz ELT

Additional Features

Spacemaker

Rotorbrake

Cargo Hook

Flitesteps

Step Handles

Wirestrike Kit

Litter Provisions

Folding Steps

Floor Protectors

Air-Conditioning

High Skid Gear

Cargo Mirror

Particle Separator

Engine Bleed Air

Door Openers

Bleed Air Heater

RH Slide Door

T/R Pedal Lockout Kit

Hard Point Kit

Major Component Summary

MR Blades	Remaining On Condition	TR Blades	Remaining On Condition
MR Hub	332	TR Hub	426
MR Grips	2832	TR Yoke	2926
MR Pitch Horns	2832	TR Gearbox	332
Upper/Lower Plates	332	Starter Generator	506
Drive Hub Set	2832	Engine Impeller	5328
Input Drive Shaft	3563	Turbine Assy	1604
Transmission	332	Turbine Wheels 1 & 2	1629
Freewheel Assy	332	Turbine Wheels 3 & 4	1629
MR Mast Pole	4266	HMU	61
MR Mast Assy	332	Fuel Nozzle	1604
Swashplate Support	332	Bleed Valve	837

Exterior

Yellow - 5/10. On arrival stripped and painted including 3 colours of customers choice.

Interior

Leather, Corporate - 5/10. On arrival new leather, carpet and interior refurbishment.

Maintenance

Delivered with Fresh Inspection and Export C of A to New Zealand.

Price

US\$1,398,500 (plus GST if applicable)

Remarks

One owner since new. No known damage. Price includes delivery to New Zealand with fresh paint and refurbished interior to customers preferences. New Zealand Certificate of Airworthiness included. Additional information to follow.

Please Contact

Thompson Aviation Limited – Martyn Thompson | www.Thompson-Aviation.com

This helicopter is being brokered by Thompson Aviation Limited. Thompson Aviation has NOT conducted a detailed inspection of the aircraft to verify mechanical condition, airworthiness or accuracy of specifications and documents. Prospective purchasers are encouraged to conduct their own independent pre-purchase inspection as Thompson Aviation makes no representations as to the airworthiness of the listed aircraft or the accuracy of the aircraft specifications.

All aircraft specifications subject to verification upon inspection and change without notice. Listed aircraft offered subject to remaining unsold or withdrawal from sale. E & OE.




THOMPSON
Aviation Limited

Martyn Thompson
martyn@Thompson-Aviation.com



www.Thompson-Aviation.com



www.Thompson-Aviation.com



www.Thompson-Aviation.com